

Side Mounted Bushing Leak



A side mounted bushing leaking between the aluminum and porcelain is repaired by the Power Services Division of Colt without draining the oil or disassembling the bushing. The repair utilizes a custom designed clamp manufactured by Colt from a low absorption, cast nylon material. The clamp is manufactured at the company's machine shop facility and is on the job site within twenty-four to thirty-six hours. A proprietary, two-part rubber like sealant is hydraulically injected into the clamp to seal the leak. This sealant has excellent dielectric properties and has had dissolved gas analysis completed.

All repairs are guaranteed for two years.