

Leaks Repaired On Distribution Transformers



The Power Services Division of Colt has developed several repair methods for making repairs to leaks on distribution transformers (up to 2500 KVA). A two week program was completed for a major mid-west utility that showed substantial savings versus removing and replacing the units. After the utility crew grounded the unit Colt technicians would clean the transformer, make any required repairs for leaks and add oil if needed. A rate schedule was developed that had a daily charge that included all parts and labor, it was determined that a Colt technician could repair two-three units per day.

All repairs are guaranteed for two years.