

CT Leaks Repaired In Place



Colt technicians have repaired thousands of transformer oil leaks using our proven injection process. One way to make a repair to a leaking CT is to encapsulate the leaking stud with a custom enclosure made from a low absorption material. The nut and wire are removed, the stud enclosure is installed over the leaking stud/studs. A nut is installed, then the wire and finally a nut to hold the wire. The completed assembly is then injected with our S-22 sealant compound.

All repairs are guaranteed for two years.