

## Leaking Radiator Drain Plug Threads With The Unit In-Service



Typical transformer radiators have a half coupling with a plug installed, located on each radiator bank on the top and bottom to facilitate draining individual radiators. These are prone to leak; Colt service trucks stock several sizes of custom repair caps that are installed over the active leak and then are injected with our S-22 sealant to stop the leak.

**All repairs are guaranteed for two years.**