

SF6 Gas Leaks Repaired Under Pressure On Bus System



SF6 gas circuit breakers and insulated bus systems are prone to leak. The picture above shows a flange that has been repaired by Colt technicians with the system in-service and under pressure. A custom manufactured repair clamp is installed and then hydraulically injected with our S-22 sealant to stop the leak.

All repairs are guaranteed for two years.